PPE Checklist Modified Respiratory Precautions

Steps for putting on PPE		Steps for taking off PPE	
	Clean hands		Gloves
2	Gown Tie top and waist	2	Clean hands
3	N95 respirator (or KN95 in Continuing Care) medical mask* Eye protection Cover nose and mouth, eye protection secured *Based on PCRA and assessment of risks and hazards, may choose to wear a medical mask with eye protection. 1. For Aerosol-generating medical procedures + suspected or confirmed COVID-19 fit-tested N95 respirator required. 2. Seal check before entering room.	4	Gown Untie at top first, then waist Clean hands
	Gloves Over cuffs	5	Facial PPE (i.e., respirator/mask plus eye protection)
REUSABLE eye protection 1. DISCARD MASK/N95 RESPIRATOR or KN95 MASK 2. DISINFECT EYE PROTECTION 3. PLACE ON CLEAN SURFACE		DISPOSABLE eye protection and mask, N95 respirator or KN95 mask with visor 1. DISCARD EYE PROTECTION AND MASK/N95 RESPIRATOR or KN95 MASK 2. REMOVE EYE PROTECTION 3. DISCARD MASK/N95 RESPIRATOR or KN95 MASK	
https://creativecommons.org/licenses/by-nc-sa/4.0/ For more information contact ipcsurvstdadmin@ahs.ca © 2022 Alberta Health Services, IPC Alberta Health Services Infection Prevention			Hand sanitizer or Soap and water

Infection Prevention & Control